


# OVERHEAD POWER LINE SAFETY


1 Locate all overhead power lines



2 Consult with the Asset Owner and follow the guidance of the GS6 Document



3 Establish the safe working distances and deploy blue cones and physical barriers



4 If work under the lines cannot be avoided, make sure you have a permit in place



5 Beware of fencing near power lines due to impressed voltage



6 Carry ladders and other equipment horizontally and utilise plant with height restrictors



7 Do not approach plant or equipment that might be in contact with the power lines



8 Stay at least 10m away from fallen power lines

